

JK

Outgoing
0150015

Q

Suzanne Steab - May 2010 Inspection Reports

From: Karl Houskeeper
To: IanMcClain@consolenergy.com; JohnGefferth@consolenergy.com ; SteveBehl...
Date: 6/22/2010 8:27 AM
Subject: May 2010 Inspection Reports
CC: ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov
Attachments: Hidden Valley May 2010.pdf; Emery Deep May 2010.pdf

Attached are the May 2010 inspection reports for Emery Deep and Hidden Valley.

Thanks,
Karl



The State of Utah

Department of
Natural Resources

Division of
Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:
OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0150015
Inspection Type:	COMPLETE
Inspection Date:	Thursday, May 06, 2010
Start Date/Time:	5/6/2010 8:00:00 AM
End Date/Time:	5/6/2010 2:20:00 PM
Last Inspection:	Thursday, April 01, 2010

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 50 Deg. F.

InspectionID Report Number: 2348

Accepted by: jheltric
5/17/2010

Permitee: **CONSOLIDATION COAL CO**
 Operator: **CONSOLIDATION COAL CO SESSER OPERATIONS**
 Site: **EMERY DEEP MINE**
 Address: **PO BOX 566, SESSER IL 62884**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

442.50	Total Permitted
248.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Jaren Jorgensen, Conso, I was present during the inspection.

Inspector's Signature: _____

Date Thursday, May 06, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!
Where ideas connect™

Permit Number: C0150015
 Inspection Type: COMPLETE
 Inspection Date: Thursday, May 06, 2010

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/015/015 was issued effective 01/06/2006 and expires 01/08/2011.

-Certificate of Insurance policy number BOG 9377 215-06, issued 11/05/2009 and terminates 11/05/2010.

-UPDES permit UT-0022616 effective 12/01/2006 and expires @ midnight 11/30/2011.

-Air Quality permit DAQE-AN0229006-05, issued July 20, 2005.

-SPCC Plan dated 10/24/06. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

3. Topsoil

The topsoil sign located by the portal access road that is to be placed on top of the berm is down. The sign needs to be put back into place so that mine personnel are aware that this a topsoil stoage area and is not to be disturbed.

Mine beltin is laid against the berm that is als a topsoil pile. The belting needs to be removed from off the topsoil storage.

4.a Hydrologic Balance: Diversions

The belting has been removed from the diversion that was identified on the previous inspection.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

First quarter 2010 pond inspections were done on 03/29/2010.

4.e Hydrologic Balance: Effluent Limitations

The March 2010 discharge monitoring reports were reviewed as part of the complete inspection. The TDS loading parameter was exceeded. The company notified DEQ of the exceedance by letter dated April 28, 2010.

7. Coal Mine Waste, Refuse Piles, Impoundments

The first quarter 2010 refuse pile inspection was done on 02/14/2010 and P.E. certified.

8. Noncoal Waste

High winds were present during the inspection. Portions of the main facility and 4th East Portal area had scattered trash. These areas were identified and the operator committed to remove the trash immediately.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-AN0229006-05 was issued on July 20, 2005. The permit remains effective.

Permit Number: C0150015
Inspection Type: COMPLETE
Inspection Date: Thursday, May 06, 2010

Inspection Continuation Sheet

Page 4 of 4

21. Bonding and Insurance

Bond #188617 December 3, 2008 is \$3,510,000.